



Toxic solution: Double wall heat exchanger required, and approved backflow protection of an ASSE 1013 required.